







TB BOX



SYMBOL	
(P)	MANUAL FIRE ALARM BOX
(H)	HEAT DETECTOR
(S)	SMOKE DETECTOR
(B)	FIRE ALARM BELL
(L)	LOCATION LAMP
(R)	END OF LINE RESISTOR 10K OHM.1/2W.

- C = WIRING BY CVW 1.5 sqmm or THW 1.5 sqmm.
 L = WIRING BY CVW 1.5 sqmm or THW 1.5 sqmm.
 A = WIRING BY CVW 1.5 sqmm or THW 1.5 sqmm.
 T = WIRING BY CVW 1.5 sqmm or THW 1.5 sqmm.
 BKC = WIRING BY CVW 2.5 sqmm or THW 2.5 sqmm.
 BKF = WIRING BY CVW 2.5 sqmm or THW 2.5 sqmm.
 PU = WIRING BY CVW 2.5 sqmm or THW 2.5 sqmm.
 PV = WIRING BY CVW 2.5 sqmm or THW 2.5 sqmm.

หมายเหตุ

- กรุณาดู FIRE ALARM BELL แบบดังรวม ให้ F11 - F20 (COMMON) แล้วต่อเข้า BKC (-) ของ FCP
- C (COMMON) 7 ZONE ต่อ COMMON ของ FCP 1 จุด

WIRING DIAGRAM FIRE ALARM SYSTEM
 10 ZONE UP (FAPN105N-R-10L)