





TB BOX

<u>SYMBOL</u>	
	MANUAL FIRE ALARM BOX
	HEAT DETECTOR
	SMOKE DETECTOR
	FIRE ALARM BELL
	LOCATION LAMP
	END OF LINE RESISTOR 10K OHM.1/2W.

C	=	WIRING BY CW	1.5 sqmm	or	THW	1.5 sqmm.
L	=	WIRING BY CW	1.5 sqmm	or	THW	1.5 sqmm.
A	=	WIRING BY CW	1.5 sqmm	or	THW	1.5 sqmm.
T	=	WIRING BY CW	1.5 sqmm	or	THW	1.5 sqmm.
BKC	=	WIRING BY CW	2.5 sqmm	or	THW	2.5 sqmm.
BKF	=	WIRING BY CW	2.5 sqmm	or	THW	2.5 sqmm.
PU	=	WIRING BY CW	2.5 sqmm	or	THW	2.5 sqmm.
PV	=	WIRING BY CW	2.5 sqmm	or	THW	2.5 sqmm.

WIRING DIAGRAM FIRE ALARM SYSTEM
5 ZONE UP (FAPN202-R-5L)